

Skyland Fire Hydrant Status



Fire Hydrants

- There are 21 Fire Hydrants in Skyland.
- 7 Fire Hydrants appear to be original to the neighborhood (late 50's, early 60's style).
- 8 Fire Hydrants do not meet code because they are too low to the ground.
- 1 Fire Hydrant has the wrong main valve diameter (4" vs 6")
- The colors (base or cap) do not meet the current standard to aid critical firefighter timelines

- The Fire Hydrants are the responsibility of the Water Utility
- The Fire Hydrants are in the Skyland GID right of way

Action:

1. Letter to Water Utility and TDFPD identifying the issues found and requesting resolution
 - Potential FH replacement
 - Potential addition of riser
 - Potential painting of FH w/ cap color correlated to flow rate

Detail from Neighborhood Survey with Kris Rowlette TDFPD

Fire Hydrant Review						
Date: 22 January 2024						
Street - Designation	Address	Fire Hydrant Color Base/top	Valve height meets code	Main Valve size	Ballard	Flow Rate
Myron - A	1008 Myron	Red/Red	No	6"	OK	
Myron - B	1030 Myron	Red/Red	No	6"	Needs update	
Myron - C	193 Ray	Red/Red	Yes	6"	OK	
Myron - D	189 Myron	Silver/Yellow	No	4"	OK	1389
Myron - E	1091 Skyland	Silver/Yellow	Yes	6"	OK	781
Skyland - F	1069 Skyland	Red/Red	Yes	6"	OK	
Skyland - G	1051 Skyland	Red/Red	Yes	6"	OK	
Skyland - H	1031 Skyland	Red/Red	Yes	6"	OK	
Skyland - I	1011 Skyland	Red/Red	Yes	6"	Missing	
Beach - J	Beach - across from 80 Skyland Ct	Yellow/Yellow	Yes	6"	OK	
Tahoe - K	135 Tahoe	Silver/Yellow	No	6"	OK	
Ponderosa - L	146 Ponderosa	Silver/Yellow	No	6"	OK	
Ponderosa - M	120 Ponderosa	Red/Red	Yes	6"	OK	
Ponderosa - N	100 Ponderosa	Red/Red	Yes	6"	OK	
Willow - O	150 Willow	Silver/Yellow	No	6"	OK	
Willow - P	1002 Red Fir	Silver/Yellow	No	6"	OK	
Carson - Q	189 Carson	Silver/Yellow	Yes	6"	OK	650
Deercliff - R	1097 Deercliff	Red/Red	Yes	6"	OK	
Deercliff - S	179 Ray	Red/Red	Yes	6"	OK	
Deercliff - T	160 Lynn	Red/Red	No	6"	Needs update	
Golden Mantle - U	1038 Golden Mantle	Red/Red	Yes	6"	OK	